

REQUEST FOR BOARD ACTION

HENDERSON COUNTY
BOARD OF COMMISSIONERS

MEETING DATE: January 7, 2013

SUBJECT: Approval to Surplus One Sheriff's Office Vehicle

PRESENTER: Sheriff Charles McDonald

ATTACHMENTS: Yes

1. Vehicle Accident Appraisal for Dodge Charger,
Plate Number 96848S

SUMMARY OF REQUEST:


The Sheriff's Office is requesting that the Board authorize the Sheriff's Office to surplus one patrol vehicle, and transfer it as a donation to Blue Ridge Community College (BRCC). The vehicle was involved in an accident, for which the insurance company has paid the accident claim. Current vehicle mileage is 96,473. The vehicle will be repaired by BRCC auto body repair students, and then will be used by BRCC for their Basic Law Enforcement Training (BLET) Program

BOARD ACTION REQUESTED:

The Board is requested to approve the request and authorize the Sheriff's Office to proceed with the transfer and donation of one patrol vehicle to BRCC.

Suggested Motion:

I move the Sheriff's Office and the County Manager be authorized to surplus one Sheriff's Office patrol vehicle and transfer it as a donation to Blue Ridge Community College (BRCC).



Administration Information

Customer Name: Sedgwick Cms - Charlotte NC Claim No.: B218407198-0001-01
 Owner Name: HENDERSON COUNTY Policy No.: _____
 Adjuster Name: TRACY MCCRADY Customer No.: SED055046
 Assignment No.: 951-211-0021

Vehicle Information

Vehicle Year: 2008 Vehicle VIN: 206066
 Vehicle Make: Dodge Vehicle Mileage: 96473
 Vehicle Model: CHARGER Plate Number: 96848S Plate State: NC
 Type of Loss: Collision Interior: Average Paint: Average

Date Information

Assignment Date: 11/5/2012 Inspection Date: 11/06/2012 Completion Date: 11/7/2012

Loss Recap Information

Recommendation: Repairable Appraisal Amount: 5968
 Repair Shop Name: Select Shop Agreed Price Reached with Shop: N
 Approx ACV: _____ Estimated Salvage _____
 Drivable: Y Parts Delay: U Approx Days To Repair: 8

Betterment		Old Damage	
Description	Amount	Description	Amount
Suggested Betterment	0.00	Total Old Damage	0.00

LKO Parts Usage

Name	City	Contact Person	Phone

Remarks

11/6 INSP AT CTY GARAGE ESTIMATE WRITTEN, CPY FAXED TO GARAGE. FILE COMPLETED AND U/L TO PDA TO FWD TO CARRIER 11/7.

PDA Appraiser: John Long Office Phone: 828-296-1706

Thank you for choosing Property Damage Appraisers

Date: 11/7/2012 10:35 AM
 Estimate ID: 9512110021
 Estimate Version: 0
 Committed
 Profile ID: ASHEVILLE

PROPERTY DAMAGE APPRAISERS

PO Box 1067, Asheville, NC 28802
 (828) 296-1706
 Fax: (828) 296-1707
 Email: pdaasheville@pdaorg.net

***** NOTICE *****
 THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL COSTS OF REPAIRS ARE THE
 SOLE RESPONSIBILITY OF THE OWNER, WHO MUST AUTHORIZE ALL REPAIRS.

 NO SUPPLEMENT WILL BE HONORED UNLESS AUTHORIZED. ALL SUPPLEMENTS
 MUST BE FAXED TO PDA AT 828-296-1707 OR EMAILED TO PDA AT
 pdaasheville@pdaorg.net (NO EXCEPTIONS).

Damage Assessed By: John Long

Appraised For: TRACY MCCRADY

Condition Code: Good
 Date of Loss: 11/5/2012
 Contact Date: 11/6/2012
 Deductible: 0.00
 File Number: 9512110021
 Claim Number: B218407198-0001-01

Type of Loss: Collision

Insured: HENDERSON COUNTY
 Owner: unk HENDERSON COUNTY
 Address: CONT CLAY THOMAS 320 WILLIAM ST, HENDERSONVILLE, NC
 Telephone: Work Phone: (828) 697-4836

Mitchell Service: 910475

Description: 2008 Dodge Charger Police
 Body Style: 4D Sed
 VIN: 2B3KA43H78H206066
 Mileage: 96,473
 OEM/ALT: A
 Color: BLACK

Vehicle Production Date: 12/07
 Drive Train: 5.7L Inj 8 Cyl 5A RWD
 License: 9884BS NC

Search Code: 848

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>MANUAL ENTRIES</u>							
1	900500	BDY *	REMOVE/REPLACE	FRT PUSH BAR	** QUAL REPL PART	189.95 *	1.5*
2	900500	BDY *	REMOVE/INSTALL	TRANSFER EMERGENCY EQUIPMENT	Existing		2.0* r
3	900500	BDY *	REMOVE/REPLACE	FRT HOOD & FDR DECALS	** QUAL REPL PART	125.00 *	0.0*
<u>Front Bumper</u>							
4		BDY	OVERHAUL	Frt Bumper Assy			3.1 #
5	002808	BDY	REMOVE/REPLACE	Frt Bumper Cover	Remanufactured	387.00	INC #
6		REF	REFINISH	Frt Bumper Cover			C 3.1
7	002680	BDY	REMOVE/REPLACE	R Frt Inr Bumper Support Bracket	4806230AD	41.85	INC
8	002661	BDY	REMOVE/REPLACE	L Frt Inr Bumper Support Bracket	4806231AD	41.85	INC
9	001766	BDY	REMOVE/REPLACE	R Frt Otr Bumper Support Bracket	480629BAC	5.95	INC
10	001767	BDY	REMOVE/REPLACE	L Frt Otr Bumper Support Bracket	480629AAC	5.95	INC
11	000021	BDY	REMOVE/REPLACE	R Frt Bumper Pin 4@4.45	6504521	17.80	INC
12	004330	BDY	REMOVE/REPLACE	L Frt Bumper Pin 4@4.45	6504521	17.80	INC
13	000029	BDY	REMOVE/REPLACE	Frt Bumper Impact Absorber	4806178AB	157.00	INC
14	000028	BDY	REMOVE/REPLACE	Frt Bumper Reinforcement (HSLA)	68100209AB	156.00	0.6 #
15		BDY	REMOVE/INSTALL	Frt Bumper Cover			INC #

ESTIMATE RECALL NUMBER: 11/07/2012 10:34:57 9512110021

Mitchell Data Version: OEM: SEP_12_V1102
 MAPP: SEP_12_V

Copyright (C) 1994 - 2012 Mitchell International
 All Rights Reserved

Page 1 of 4

Software Version: 7.0.481

Date: 11/7/2012 10:35 AM
 Estimate ID: 9512110021
 Estimate Version: 0
 Committed
 Profile ID: ASHEVILLE

Line #	Code	Qty	Description	Part #	Price	Unit
<u>Grille</u>						
16	002807	BDY	REMOVE/REPLACE	Grille	68148158AA	325.00 INC #
<u>Front Lamps</u>						
17	000071	BDY	CHECK/ADJUST	Headlamps		0.4
18	000072	BDY	REMOVE/INSTALL	R Frt Combination Lamp		0.3 #
19				FRT LAMPS ARE AN OPEN ITEM		
20	000073	BDY	REMOVE/INSTALL	L Frt Combination Lamp		0.3 #
21		BDY	REMOVE/INSTALL	Air Cleaner Assy		INC
<u>Hood</u>						
22	002683	BDY	REMOVE/REPLACE	Hood Panel	4575725AC	1,205.00 1.3
23		REF	REFINISH	Hood Outside		C 2.7
24		REF	REFINISH	Add For Hood Underside		C 1.4
<u>Cooling</u>						
25	000148	BDY	REMOVE/INSTALL	Radiator		2.0
26				RADIATOR IS AN OPEN ITEM. TANK IS FULL		
27	000154	BDY	REMOVE/REPLACE	Cooling Fan Shroud	5137717AB	115.00 0.4 #
28	000155	BDY	REMOVE/REPLACE	R Cooling Fan Blade	5137713AA	28.35 INC #
29	000156	BDY	REMOVE/REPLACE	L Cooling Fan Blade	5137713AA	28.35 INC #
<u>A/C Heater/Ventilation</u>						
30	004473	MCH	REMOVE/REPLACE	Air Cond Condenser/Trans Cooler -M	ORDER FROM DEALER	260.00 1.4 #
31		MCH	REMOVE/REPLACE	Evacuate & Recharge A/C -M		1.4
<u>Front Fender</u>						
32	000255	REF	BLEND	R Fender Outside		C 0.8
33	001902	BDY	REPAIR	L Fender Panel	Existing	2.5*#
34		REF	REFINISH/REPAIR	L Fender Panel		C 1.0*
35				MODIFIED REFINISH WITH FULL CLEAR COAT		
<u>Front Inner Structure</u>						
36	002785	BDY	REMOVE/REPLACE	Upr Front Body Tie Bar (HSLA/Composite)	4806163AE	325.00 1.4 #
37		REF	REFINISH	Upper Tie Bar		1.0
38	001911	BDY	REMOVE/REPLACE	Front Body Lower Tie Bar (CRSSS)	5065240AF	172.00 0.5
<u>Body Components</u>						
39	931009	MCH	ALIGN	Front/Rear Suspension	Sublet	69.95 * 0.0*
<u>Additional Costs & Materials</u>						
40	936000		ADD'L COST	Fron & Oil		25.00 *
41	936003		ADD'L COST	Coolant		12.00 *
<u>Rocker/Pillars/Floor</u>						
42	001886	BDY	REMOVE/INSTALL	L Rocker Moulding		0.4
<u>Additional Costs & Materials</u>						
43	936012		ADD'L COST	Hazardous Waste Disposal		5.00 *
44	936014		ADD'L COST	Flex Additive		8.00 *
<u>MANUAL ENTRIES</u>						
45	900500	BDY *	REPAIR	Frame/Rack Setup	Existing	2.0*
46	900500	FRM *	REPAIR	Unibody Pull	Existing	2.0*
<u>ADDITIONAL OPERATIONS</u>						
47		REF	ADD'L OPR	Clear Coat		2.6
48	933005	BDY	ADD'L OPR	Restore Corrosion Protection		5.00 * 0.3*
49	933016	REF	ADD'L OPR	Mask For Overspray		8.00 *
<u>Additional Costs & Materials</u>						
50			ADD'L COST	Paint/Materials		352.80 *

* - Judgment Item
 # - Labor Note Applies
 ** QUAL REPL PART - Quality Replacement Parts
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

Date: 11/7/2012 10:35 AM
 Estimate ID: 9512110021
 Estimate Version: 0
 Committed
 Profile ID: ASHEVILLE

WEAVER AFTERMARKET
 9001 STITT ST.
 MONROE
 NC 28110
 (704) 261-0101 (800) 282-0723

5 ** CH1000913R 387.00

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary		
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals			Amount
Body	19.0	42.00	5.00	0.00	803.00	Taxable Parts		3,604.85
Refinish	12.6	42.00	8.00	0.00	537.20	Sales Tax	@ 7.750%	279.38
Frame	2.0	50.00	0.00	0.00	100.00			
Mechanical	2.8	60.00	0.00	69.95	237.95	Total Replacement Parts Amount		3,884.23
					Non-Taxable Labor			1,678.15
					Labor Summary	36.4		1,678.15
III. Additional Costs						IV. Adjustments		
					Amount			Amount
Taxable Costs					37.00	Insurance Deductible		0.00
Sales Tax			@ 7.750%		2.87	Customer Responsibility		0.00
Non-Taxable Costs					365.80			
Total Additional Costs					405.67			
Paint Material Method: Rates Init Rate = 28.00 , Init Max Hours = 99.9, Add'l Rate = 0.00								
						I. Total Labor:		1,678.15
						II. Total Replacement Parts:		3,884.23
						III. Total Additional Costs:		405.67
						Gross Total:		5,968.05
						IV. Total Adjustments:		0.00
						Net Total:		5,968.05

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AUTOMOBILE PARTS NOT MADE BY THE ORIGINAL MANUFACTURER. PARTS USED IN THE REPAIR OF YOUR VEHICLE MADE BY OTHER THAN THE ORIGINAL MANUFACTURER ARE REQUIRED TO BE AT LEAST EQUIVALENT IN TERMS OF FIT, QUALITY, PERFORMANCE AND WARRANTY TO THE ORIGINAL MANUFACTURER PARTS THEY ARE REPLACING.

Point(s) of Impact
 12 Front Center (P)

Date: 11/7/2012 10:35 AM
Estimate ID: 9512110021
Estimate Version: 0
Committed
Profile ID: ASHEVILLE

Insurance Co.: Sedgwick Cms - Charlotte NC
Address: 5260 Parkway Plaza Blvd
Ste 190
Charlotte, NC 28217
Work Phone: (800) 822-4469
Fax Phone: (704) 423-6226

Inspection Site: COUNTY GARAGE
Inspection Date: 11/6/2012

Body Shop: OWNER'S CHOICE

BY PROVIDING A COPY OF KNOWN DAMAGES, THIS IS NOT AN ACCEPTANCE OF
LIABILITY, OR CONFIRMATION OF COVERAGE, OR THAT PAYMENT IS TO FOLLOW.

PDA SPECIFIES THAT ALL REPAIRS AND/OR PART REPLACEMENTS LISTED HEREIN
BE MADE IN STRICT ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.

DEDUCTIBLES MAY/MAY NOT BE ADDRESSED OR INCLUDED IN THIS ESTIMATE.
IF APPLICABLE, THE REPAIRER SHOULD COLLECT IT FROM THE VEHICLE OWNER
PRIOR TO THE RELEASE OF THE REPAIRED VEHICLE.

THIS ESTIMATE IS SUBJECT TO THE REVIEW AND APPROVAL OF THE CARRIER.

ESTIMATE RECALL NUMBER: 11/07/2012 10:34:57 9512110021

Mitchell Data Version: OEM: SEP_12_V1102

Software Version: MAPP-SEP_12_V
7.0.481

Copyright (C) 1994 - 2012 Mitchell International
All Rights Reserved

Page 4 of 4

Review Results: Failures (0), Warnings (8)

Owner: unk HENDERSON COUNTY, Claim #B218407198-0001-01
 Vehicle: 2008 Dodge, Charger
 Profile: Sedgwick no AM Version: 4

Estimate lines

Line	Severity	Description	Actual	Guideline	Override	Notes
35	Warning	Clear Coat exceeds carrier threshold	2.80	2.50		Yes
INC CC COVER						
22	Warning	Hood Panel - 14l - consider LK no AM	OE	LK		Yes
NA						
13	Warning	Frt Bumper Impact Absorber - 19h - consider RM LK AM	OE	LK AM RM		Yes
NA						
14	Warning	Frt Bumper Reinforcement - 19h - consider RM LK AM	OE	LK AM RM		Yes
NA						
28	Warning	R Cooling Fan Blade - 23h - consider LK AM	OE	LK AM		Yes
NA						
29	Warning	L Cooling Fan Blade - 23h - consider LK AM	OE	LK AM		Yes
NA						
27	Warning	Cooling Fan Stroud - 23h - consider LK AM	OE	LK AM		Yes
NA						

Profile (rates, taxes, amounts)

Line	Severity	Description	Actual	Guideline	Override	Notes
		Profile items Passed				

Administrative Information

Line	Severity	Description	Actual	Guideline	Override	Notes
	Warning	Vehicle Options missing				Yes
POLICE NOT LISTED						

Compliance Utility Version 4.1.0.6

Sedgwick Claims Management Services, Inc
 P O Box 14436
 Lexington, KY 40512-4436

DATE	CHECK AMT	CHECK NO.
11/15/2012	4,688.67	0037082186
PAYEE		TAX ID
HENDERSON COUNTY		
SCMS UNIT	PAGE	
184 Sedgwick Claims Management Services	1	

RETURN SERVICE REQUESTED



HENDERSON COUNTY
 112 FIRST AVE WEST
 HENDERSONVILLE, NC 28792-5008

Claimant Name	Loss Date	Claim Number	SSN
HENDERSON COUNTY	10/09/2012	B218407198-0002-01	
Amt Paid: 4688.67		Description: Miscellaneous CL/Other	
Dates: 10/09/2012 - 11/14/2012		Comment: Damages to 08 Dodge Charger	

FOR SECURITY PURPOSES, THE FACE OF THIS DOCUMENT CONTAINS A BLUE-GREEN BACKGROUND PRINTED ON ARTIFICIAL WATERMARK PAPER

VOID VOID VOID VOID VOID VOID VOID VOID

Sedgwick Claims Management Services, Inc
 On behalf of
 NCACC Liability and Property Pool

ORIGIN 1841278 CHECK DATE 11/15/2012 CHECK NO. 0037082186

PAY ONLY **4688.67**

PAY Four Thousand Six Hundred Eighty Eight And 67/100 Dollars* \$4,688.67

TO THE ORDER OF HENDERSON COUNTY

Wachovia Bank, N.A. Wilmington, DE

NC Counties of Liability and P. Principal
 Sedgwick Claims Management Services, Inc., Agent
 BY: *Bob Blankenship*

VOID AFTER 60 DAYS *EBP*

SIGNATURE HAS A BLUE-GREEN BACKGROUND - BORDER CONTAINS MICROPRINTING

⑈0037082186⑈ ⑆031100225⑆ 2079950059703⑈