

Back Door

NO WORK TO BE
DONE IN THIS
ROOM

Demo Existing fireplace, mantle, Hearth

Front Door

ALT 4. Window Repair

COMMON AREA

Existing drain to be
capped off below
slab

Existing Electric Panel

KITCHEN

Wall

