



NO WORK TO BE
DONE IN THIS
ROOM

Demo Existing fireplace, mantle, Hearth

COMMON AREA

KITCHEN

Demo Existing Cabinets, Sink, Appliances

Back Door

Front Door

Existing drain to be
capped off below
slab

Existing Electric Panel

ALT 4. Window Repair